

NEW PRESSURE SENSOR

DESCRIPTION:

A new pressure sensor, without a support is replacing an assembly with support.

SOLUTION:

For 3 types of dishwashers (60/45/55) there are 3 different ANC codes. The difference is only on the length of the hose, that is different for each platform. The other components of the assembly are the same. In case of exchange, the following components need to be changed:

SPARE PARTS:

